NORTH WESTERN RAILWAY

DIVISIONAL SAFETY OFFICE **IODHPUR** Dated 17-04-2025

Letter No. 1AT/Safety/JU/Hq Safety Drive-10/ 2025

<u>मु. संरक्षा अभियान - 10/2025</u>

Sr. DOM, Sr. DCM, Sr. DME/C&W/, Sr. DEN/Cord., Sr. DME/P, Sr. DSC, Sr. DEE/G, Sr. DEE/TRD, Sr. DSTE

Sub: Special Safety Drive -Fire safety in trains.

Ref: (i)Railway Board's Letter No. 2025/Safety-1/3/4 dated 16.04.2025 (Copy enclosed).

(ii) No. NWR/HQ/Safety/SD/10/25, dated 17.04.2025.

Vide above referred letter, a 15 days special safety drive w.e.f. 17.04.25 on "fire safety in train" has been issued by RB.

Therefore, all concerned BOs as mentioned above are requested to conduct the safety inspection covering all aspects of fire safety in passenger carrying train, including special trains, emphasizing on the points mentioned in attached annexure A and fill the Google form (link given below).

https://forms.gle/Utia6ECWP2bUqRpp6

DA- As Above.

Sr. Divisional Safety Officer North Western Railway, Jodhpur

C/ DRM/JU - For kind information please.

NORTH WESTERN RAILWAY

Headquarter Office

Jaipur

Date: 17.04.2025

No. NWR/HQ/Safety/SD/10/25

Safety Drive No. 10/2025 (RB Safety Drive No. 02)

All PHODs - NWR

DRMs - AII, BKN, JP, JU

Sub: Special Safety Drive No. 02 - Fire safety in trains.

Ref: Railway Board's Letter No. 2025/Safety-1/3/4 dated 16.04.2025 (Copy enclosed).

Vide above referred letter, a 15 days a special safety drive w.e.f. 17.04.25 on "fire safety in train" has been issued by RB.

Therefore, official of HQ and divisions are requested to conduct the safety inspection covering all aspects of fire safety in passenger carrying train, including special trains, emphasizing on the points mentioned in attached annexure and fill the Google form (link given below).

https://forms.gle/Utia6ECWP2bUqRpp6

Record of trains, stations, coaches inspected and personnel involved should be maintained by Safety branch of division.


For PCSO/NWR

DA- As above

Copy to:-

Secretary to GM for kind information of GM Secretary to AGM for kind information of AGM Sr. DSOs- AII, BKN, JP, JU- for necessary action and follow up.

भारत सरकार GOVERNMENT OF INDIA रेल मंत्रालय MINISTRY OF RAILWAYS (रेलवें बोर्ड RAILWAY BOARD)



क. 2025/संरक्षा-1/3/4

नई दिल्ली, दिनांक 16-04-2025

General Managers All Zonal Railways

rend priside to A Salter Silveria.

Chairman & Managing Director Konkan Railway Corporation Limited

Sub: Special Safety Drive No. 02 - Fire safety in trains

A Special Safety Drive of 15 days is to be launched from 17.04.2025 covering all aspects of fire safety in passenger carrying trains. Some of the important points that need to be covered during the drive are mentioned at Annexure A to this letter. All these need to be ensured and other related points also seen.

All passenger carrying trains, including special trains, must be covered during this drive. Record of trains, stations, coaches inspected and the personnel involved should be maintained by the Safety Branch of Divisions and Safety Department of Zonal Railways.

Daily progress of the drive, including Train Nos. checked/ Stations inspected and deficiencies noticed must be uploaded on SMDMS and filled in the google form available at the link https://shorturl.at/uGP5N and also at the QR code given below.



Upon conclusion of the drive, a consolidated report should be emailed to edmesafety@gmail.com and sosafetydm@gmail.com

्राज्य) का॰ निदेशक यां इं (संरक्षा)

Important Points to be Covered during Fire Safety Drive

No Unauthorised carriage of inflammable/explosive materials, gas cylinders, gas canisters & solid fuel tablets used by campers for portable cooking, burning sigrees and stoves, fireworks, poll posters etc in passenger carrying trains.

No stacking of items in corridors, near doorways, in pantry car corridors that would ii.

hinder easy egress of passengers in emergency.

Proper supervision at parcel booking offices; No misdeclaration of goods in parcel iii. booking; Ensuring no residual fuel in two-wheelers accepted for carriage; Ensure packaging conditions for safe carriage of goods are followed.

No flame-based cooking, no gas cylinders, only authorised capacity heating coils, no iv. extension boards used, no unauthorised tapping, no tampering with fuses/MCBs in

pantry cars.

No smoking, no sale of cigarettes, bidis, matches, lighters in trains or on platforms. V.

No gaps in coach panels, junction boxes etc in coaches and coach toilets so that loose vi.

paper and rubbish cannot be stuffed into the panel voids

No loose or hanging wires, no bypassed fuses, no bypassed MCBs in coaches; MCBs, vii. fuses of only proper ratings used; Holes/ gaps in electrical panels are sealed to prevent rodent entry; All electrical panels have properly locked doors; No plastic dustbins in coaches; Proper maintenance of electrical equipment;

No unauthorised use of high wattage equipment in mobile charging sockets. viii.

No heat affected sockets, switches etc with melting signs near socket holes. ix.

Proper maintenance of generator rooms in power cars ensuring all the requisite provisions for fire safety have been meticulously followed.

Proper maintenance of engine rooms/ DPCs in DEMUs ensuring all the requisite xi.

provisions for fire safety have been meticulously followed.

Proper maintenance of motor coaches of MEMU/ EMU ensuring all the requisite xii. provisions for fire safety have been meticulously followed.

Availability of AC Mechanic and Power car escorting staff at the right place. xiii.

Fire extinguishers of appropriate type with adequate life in good condition have been xiv.

provided in coaches.

AC coaches have been provided with Fire and Smoke Detection System (FSDS); XV. FSDS is functional, sensors are not blocked especially in toilets, brake valve connection of FSDS is not isolated and is locked/sealed.

Pantry car and power car have been provided with Fire Detection and Suppression xvi. System (FDSS); FDSS is not isolated; automatic suppression system magnet valve (if provided) is not isolated; this magnet valve is sealed against tampering; nitrogen cylinder pressure is adequate; water cylinders are full.

Fire safety posters, no smoking signs have been provided. xvii.

Procedure for locking of coaches, rakes is followed at the time of stabling to prevent xviii. miscreant activity.

On-board staff are aware of basic fire safety procedures; Staff know how to operate xix. fire extinguishers, manual fire suppression system of FDSS.